
Lockout…Tagout – Remember to Lockout and Tagout Infographic




SEVEN STEPS FOR LOCKOUT/TAGOUT:
1 Prepare for shutdown
2 Shutdown the machines or equipment
3 Disconnect the energy-isolating devices
4 Apply the lockout or tagout devices
5 Render all stored and residual energy safe
6 Verify the isolation and deenergization of the machine or equipment prior to starting work
7 Reactivate following specific procedures
SPECIFIC PROCEDURES APPLY TO EACH STEP!
Compliance with the OSHA Lockout/Tagout Standard prevents an estimated 120 fatalities and 50,000 injuries each year.
Taken from the "Lockout/Tagout: Make No Mistake" training program, an OSHA compliance training program that addresses the General Industry Standard for Lockout/Tagout.