


Plastic Molding Safety Infographic





WARNING



Moving platens and dies on PLASTIC INJECTION MOLDING MACHINES can crush, dismember, snag, hit, and entrap, causing serious injury or death.

- Use safeguards to protect individuals.
- Keep hands and body clear while operating.
- Restrain loose clothing and long hair.
- Do not wear jewelry.

Dies, die parts, and plastic material can be ejected from point of operation, causing serious injury or death.

- Use safeguards to protect individuals.
- Always wear personal protective equipment.

Use electrically interlocked safety blocks, platen locks, or other die/platen support means when repairing, adjusting, or cleaning. Lock out all energy before servicing.

This sign is not intended to cover all safety hazards.

 SAFETY | 2018-2019 | 800-777-1234 | 123456789

Source: <https://www.creativesafety.com>