

Power Press Safety Infographic





DANGER

CLOSING RAM AND DIE

Do not operate this machine until you read and understand the following safety precautions.

NEVER operate this machine unless you have been fully trained and have received and understand all operating instructions.

NEVER place any part of your body in the die area.

NEVER place any part of your body where it can be struck or crushed by part movement.

NEVER operate this machine without the use of a point-of-operation safeguard that will protect you from injury.

NEVER work on this machine unless power is off, the flywheel is at rest, safety blocks are used between the dies, and all energy (electrical, air, hydraulic, etc.) is in a zero state.

ALWAYS use hand tools for feeding and retrieving material from the point of operation or any other hazardous part of the machine.

You are exposed to moving machine parts that can crush, dismember, and cause death. Never place your hands or any part of your body in this machine.



DO NOT REMOVE OR COVER THIS WARNING!

WasteStickers.com 800-331-9061 WS6X3115

Source: <https://www.rockfordsystems.com>