## Delivery Driver Dies After Being Crushed



## Could This Have Been You?

On average, 5,000 to 6,000 workers are killed each year. Learn from the following reports of real workplace fatalities to avoid a similar fate.

The driver was in the process of unloading the truck for his employer when the incident occurred. The victim had parked the truck, designed with an airactivated braking system, in a parking lot about 25 feet (7.6 meters) from the back of a building where he was making a delivery.

The truck was parked on a slight incline with its rear door facing the back door of the market. The victim was found pinned between the truck's bumper and a building drainpipe. The parking brake had not been secured, allowing the truck to roll backwards and pin the victim.

Employees from the store called 911 and the victim was taken to a local hospital where he remained for the next two days. His condition gradually deteriorated and he died from massive internal injuries.

## **Recommendations:**

The investigator concluded that in order to prevent similar occurrences in the future, employers should provide delivery drivers with some form of roll prevention device such as wooden blocks or chocks. Drivers should be required to use them behind rear tires to prevent trucks from rolling backwards when parked.

In addition, manufacturers and equipment designers should equip commercial vehicles with an automatic alarm system that is activated when the emergency brake has not been set.