

Floor Openings Picture This



The railing arrangement in this photo is in some ways more dangerous than the floor hole it's guarding:

- There's no intermediate railing; and
- The post ends jutting out from over the top railing are uncapped and could cause serious damage if workers stumble into them.

Moral: Make sure your floor hole guarding arrangements meet OSHA standards and don't expose workers to additional hazards.