
Picture This! Hazards by the Barrel Full





Scaffold safety has plunged to a new low in this photo. Barrels and boards stacked high have created a precarious working platform for these two workers. Like a house of cards, everything could come crashing down at any moment. (Source unknown)