Picture This! Maintenance Acrobatics



He’s maintaining three points of contact all right, but this worker has forgotten all about ladders or fall protection equipment and is hanging one-handed from a railing off the side of a building as he performs exterior maintenance. One small slip of a hand or foot could lead to his downfall. (Source unknown)